



The fitting of ISOEDGE is simple but IMPORTANT. Omissions and faulty workmanship can lead to REJECTION by the Building Control Body and SOUND TEST FAILURES necessitating COSTLY REPAIRS.

FOR FURTHER INFORMATION CONTACT THERMAL ECONOMICS TECHNICAL DEPARTMENT ON 01582 544255